Work Orde Thursday, October												Page 1
Revision ID:	D044-662-013		N	Accept				s	etup			
		Start Qty: 4.00 Req'd Qty: 4.00			Cust Item l Customer:	ID:			7	Stop		
Approvals:	Process Plan:		Date: <u>/0-/0-7</u> 2			ate:		R		Start Stop		
Sequence ID/ Work Center ID		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr N/A	Revisi Rev N	on Nbr										
100 DC Document Control		DOCUMENT CONTRO Memo	DL bluefile & type labels per PF	0.00 0.00 PPD044-662-013	CHG 001 50/0	ils		4)d	01 E	36	10-11	-Us
110 Packaging Packaging	P	Pick Kit . Memo		0.00					dlu	16	(y)	5/
120 QC	Ç	QC4- 100% Inspect kits Memo	for completeness	0.00	oiolu lib			(44	ر(

Quality Control

Dart Ae	rospace	e Ltd							, «
W/O:			W	ORK ORDER CHANGE	S				,
DATE	STEP	PROC	EDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									•
<u>; </u>									
	:								
Part No	•	PAR #:	Fault Cat	tegory:	NCR: Yes	No DQ	A:	Date:	
	R	esolution:	Dispositi	ion:	QA: N/C C	osed:		Date: _	
NCR:		We	ORK ORI	DER NON-CONFORMAN	NCE (NCF	R)			
DATE	CTED	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector
ļ									

Work Order ID 63149

Thursday, October 21, 2010 3:53:06 PM



Page 2

Item ID:

D044-662-013

Accept

Qty

Setup Start



Revision ID:

Start Date:

Item Name: Bearpaw

10/21/2010

Start Qty: 4.00

Required Date: 10/28/2010

Req'd Qty: 4.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____

Date: **Tooling:** Date: _____

SPC (Y/N):

Date:

Tool ID

Date:

Tool # Plan

Code

Run

Stop

Stamp

Sequence ID/

Work Center ID

130

Packaging

Packaging

Operation

Description

Set Up/ **Run Hours**

0.00

0.00

Packaging

Identify and pack for shipping as per PPP D044-662-013

Location:

PPP Rev:

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Start

Stop

Reject Insp.

Reject Accept Qty Number

									•
W/O:			WO	RK ORDER CHANGI	ES		,		
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•									
		·							
			,						
, , , , , , , , , , , , , , , , , , ,									
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A :	_ Date: _	
	Re	esolution:	Disposition	:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	()			
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
JAIL		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section	on C	Chief Eng	QC Inspector
					-				
l									2
						,			:

Picklist Print Parent Item:

Thursday, October 21, 2010 3:53:10 PM

Work Order ID: 63149

D044-662-013

Parent Item Name: Bearpaw



Start Date: 10/21/2010

Required Date: 10/28/2010

Start Qty: 4.00

Required Qty: 4.00

Comments:

IPP Rev:A New Issue 07-01-30 JLM

IPP Rev:B As per IIN 044-662 REV D 07-03-28 JLM

Component Item ID/	Replacement		Bin	Primary	Last	Route	Unit of	Qty on	Qty per Kit	Total	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand		Qty	Issued	Issued	Status
- D3601-1 		Manufactured	No			110	Each	70.0000	8	132/11/	165		
* .				Location	<u>n</u>	Loc C	<u>Oty</u>	Loc Code					
	-			ST074			70		_	7	_		
D2182B		Manufactured	No	•	51604	110	70 f	152.9192	1.5	6.315789	9		
Rubber Cushion	7	هما د		101	1 < " 1					11/16	کرد		
2 . 11	(K. 16-11	د ۱۶ ه رو	دې د	Location ST402A		Loc C	<u>)ty</u> 2.77	Loc Code					
, xA	. 0	mande			30872		3.67		_		-		
	Men	300			39986		9.1		_		-		
	8	lolulo		ST410		130.14			_		-		
-D2529 \		Manuelantum	Ma		52649	130.14		401 0000	_		-		
Washer		Manufactured	No .			110	Each	481.0000		32 12/11	1165/	1	
				Locatio	<u>n</u>	Loc C	<u>Oty</u>	Loc Code					
		2		ST017			481			_			
		to .			61979		481		_	32	_	1	
D3556-1	Ш	Manufactured	No	^t va		110	Each	43.0000	4	10/11	1168	1/4	
Clamp				<u>Locatio</u>	<u>n</u>	Loc C	<u>)ty</u>	Loc Code			,		
				ST458			43		_		_		
					51405		43		_	16			

Dart Aerospace Ltd

W/O:		V-1,2.1	WO	RK ORDER CHANG	ES		····			•
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	ı	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			7.1							
					<u>.</u>					
										,
								,		
					į					
Part No	:	PAR #:	Fault Categ	ory:	_ NCR: Y	es N	DQA:		_ Date: _	
	Re	esolution:	Disposition	:	_ QA: N/C	Clos	ed:		Date:	
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (N	CR)				
DATE	STEP	Description of NC	<u> </u>		ion B	0	Verificat		Approval	Approval
	0121	Section A	Initial Chief Eng	Action Description Chief Eng		gn & ate	Section	C	Chief Eng	QC Inspector
	į 									
				•						
						•				
		·								
					ļ		İ			

Thursday, October 21, 2010 3:53:10 PM

Work Order ID: 63149 Parent Item: D044-662-013 Parent Item Name: Bearpaw Start Date: 10/21/2010 **Required Date: 10/28/2010** Start Qty: 4.00 Required Qty: 4.00 D3529-1 Manufactured No 110 Each 1.0000 Bearpaw Location Loc Oty Loc Code ST495 31589 AN4-15A Purchased No 110 Each 593.0000 Location Loc Qty Loc Code ST 112 115374 112 ST358 481 114784 9 115108 72 115371 100 115936 300 AN960JD416 NAS1149D0463J Purchased No 110 Each 24.0000 Washer Location Loc Oty Loc Code ST300 24 113288 24

Dart Aerospace Ltd

W/O:			WO	RK ORDER CHAN	GES				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					· · · · · · · · · · · · · · · · · · ·			Prod Mgr	•
					<u> </u>				
									
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	\ :	Date: _	
	Re	solution:	Disposition	ı:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCF	R)	,	···	
DATE	STEP	Description of NC			ection B	Verific	ation	Approval	Approval
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section	on C	Chief Eng	QC Inspector
						,	·		

Thursday, October 21, 2010 3:53:10 PM

Work Order ID: 63149

Parent Item:

D044-662-013

Parent Item Name: Bearpaw



Start Date: 10/21/2010

Required Date: 10/28/2010

Required Oty: 4.00

Start Qty: 4.00

AN4-14A -

Purchased

Purchased

No

No

110

Each 187.0000

Location	<u>n</u>	Lo	e Oty	Loc Code
ST357			171	
	114752		1	
	115371		70	
	115936		100	
ST358			16	
	113359		16	
		110	Each	3,253.000

MS21042L4

Location Loc Oty Loc Code ST300 3253 113422 68 114523 8 114718 16 114784 32 115108 129 115589 1900

1100

115621

Dart Ae	rospace Li	td						•
W/O:			WORK ORDER C	HANGES				•
DATE	STEP	PR	OCEDURE CHANGE		Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							!	
Part No);	PAR #:	Fault Category:	NCI	R: Yes	No DQA: _	Date: _	
	Reso	olution:	Disposition:	QA	: N/C CI	osed:	Date: _	
NCR:			WORK ORDER NON-CON	FORMANCE	(NCF	₹)	<u> </u>	• •
DATE	STEP	Description of NC	Corrective Action		Sign 8	Verification C	n Approval	Approval OC Inspector

NCR:			WORK ORD	ER NON-CONFORMAN	CE (NCR)			
		Description of NC		Corrective Action Section B				A
DATE	STEP Description of NC Section A		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspecto
•								
					ŀ			
				·				
								:
								:
		•						

Page 7 of 7



Qty -011	Qty -013	Qty -041	Part Number	Description
Х			D044-662-011	BEARPAW INSTALLATION
	X,		D044-662-013	BEARPAW INSTALLATION
		Х	D044-662-041	WEARPLATE KIT
4	4		D2182B045	Rubber Cushion
	-	4	D2274 '	Radius Block ·
8	8	4	D2529	Washer
2			D3075-1	Bearpaw
	2		D3529-1 #	Bearpaw
4	4	· · · · · · · · · · · · · · · · · · ·	D3556-1	Clamp
		4	D3565-1	Wearplate
8	′ 8		D3601-1/	Radius Block
		4	AN4-12A	Bolt
4	4	***************************************	AN4-14A ,	Bolt
4	. 4		AN4-15A '	Bolt
		4	AN4-16A	Bolt
8	8		AN960JD416	Washer
8	8	4	MS21042L4 /	Nut (or MS21042-4)